








0°C ... +35°C	0°C ... +35°C	40 mm	10 / 13 mm 1...2,5...4 mm²



7 520 05

10 AX - 250 V~

≤ 2,5 mm²

13 mm

7 520 05
+ 0 676 84

10 AX - 250 V~

≤ 2,5 mm²

13 mm

7 520 06 / 16 (10 AX)
7 520 27 (16 AX)

10 AX / 16 AX - 250 V~

≤ 2,5 mm²

13 mm

7 520 06 / 16 (10 AX)
7 520 27 (16 AX)
+ 0 676 86

10 AX / 16 AX - 250 V~

≤ 2,5 mm²

13 mm

7 520 06 / 16 (10 AX)
7 520 27 (16 AX)
+ 7 520 57

10 AX / 16 AX - 250 V~

≤ 2,5 mm²

13 mm

7 520 06 / 16 (10 AX)
7 520 27 (16 AX)
+ 6 650 90

10 AX / 16 AX - 250 V~

≤ 2,5 mm²

13 mm

7 520 07

10 AX - 250 V~

≤ 2,5 mm²

10 mm

7 520 07
+ 6 650 90

10 AX - 250 V~

≤ 2,5 mm²

10 mm

7 520 08 / 28

10 AX - 250 V~

≤ 2,5 mm²

13 mm

7 520 08 / 28
+ 0 676 86

10 AX - 250 V~

≤ 2,5 mm²

13 mm

7 520 08 / 28
+ 7 520 57

10 AX - 250 V~

≤ 2,5 mm²

13 mm

7 520 08 / 28
+ 6 650 90

10 AX - 250 V~

≤ 2,5 mm²

13 mm

7 520 10

10 AX - 250 V~

≤ 2,5 mm²

13 mm

7 520 10
+ 7 520 58

10 AX - 250 V~

≤ 2,5 mm²


13 mm

7 520 10
+ 0 676 88

10 AX - 250 V~




≤ 2,5 mm²

13 mm







12 - 48 V~ ~~250 V~~~




12 - 48 V~




0 676 87




250 V~





0 676 84
86
88



7 520 57
58



6 650 90
91

	0 676 84	0 676 86	0 676 87	0 676 88	6 650 90	6 650 91	7 520 57	7 520 58
7 520 01	✓	—	—	—	—	✓	—	—
7 520 02	—	—	—	—	—	—	—	—
7 520 03	—	—	—	—	—	—	—	—
7 520 05	✓	—	—	—	—	—	—	—
7 520 06 / 16 / 27	—	✓	—	—	 ✓	—	✓	—
7 520 07	—	—	—	—	✓	—	—	—
7 520 08 / 28	—	✓	—	—	 ✓	—	✓	—
7 520 10	—	✓	—	✓	—	—	✓	✓
7 520 11 / 12	—	✓	—	—	—	—	—	—
7 520 13	—	—	✓	—	—	—	—	—
7 520 17	—	✓	—	—	—	—	—	—
7 520 18	—	✓	—	—	—	—	—	—
7 520 41	—	—	—	—	—	✓	—	—